



Testing laboratory no. 1152.1, accredited by Czech Accreditation Institute in accordance with ČSN EN ISO/IEC 17025:2018

## LABORATORY REPORT NO. 02588

Client <sup>#</sup>	VIF, s.r.	0.					
Client	Volutov	á 2523, 15800 Praha  5 - Stodůlky					
Sample no.	02588		SGS order	3666			
Product <sup>#</sup>		diesel fuel					
Sample specification <sup>#</sup>		Socar Petroleum / VIF Azerbaijan MMC + 1000ppm SDA summer					
Sample quantity		1,0 liter					
Sampling date§							
Sampling place <sup>§</sup>		-					
Sampled by		Sampled by client					
Sampling within sco accreditation - meth		Sampling out of accredita	ation range				
Submitter							
Sample reception da	ite	27.03.2024	NSephilaborator C. 1155				
Report approval dat	e	02.04.2024	The COO				
Report issued by		Šárka Jančová					
Issue date: 02.04.20	24	Approved by:	Šárka Jančová <sup>ch Republice</sup> Metrologist				

The results shown in this laboratory report specifically refer to the sample tested. If laboratory is not responsible for sampling results specifically refer to the sample as received. All tests have been performed using the latest revision of the methods indicated, unless specifically marked otherwise on the report. Precision parameters apply in the determination of the above results. Users of the data shown on this report should refer to the latest published revisions of ASTM D-3244, IP 367, ČSN EN ISO 4259+1 a ČSN EN ISO 4259+2. This Test Report is issued under the Company's General Conditions of Service (copy available upon request or on the company website at http://www.sgsgroup.cz/cs-CZ/Terms-and-Conditions.aspx). Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. This report shall not be reproduced except in full, without the written approval of the laboratory.

Tests out of the accreditation range are identified by a code explained bellow the table of results.

Information marked with the symbol "#" is provided by the client and the testing laboratory no. 1152.1 is not responsible for them. If sampling is not held by SGS employee, information marked with symbol "§"is provided by the client and the testing laboratory no. 1152.1 is not responsible for them.

SGS Czech Republic, s.r.o.

Natural Resources, Testing Laboratory, U Trati 42, 100 00 Prague 10, Czech Republic Billing address: K Hájům 1233/2, 155 00 Prague 5, Czech Republic IN: 48589241, registered at Municipal Court Prague, Section C, Insert 18205, on 8.3.1993 t +420 274 021 310 e sgs.czech@sgs.com www.sgsgroup.cz

## Laboratory report no. 02588

Code	Test descriptions or parameters	Unit	Result	Date of test	Testing method		
12 Cetane number on engine			60,6	27.03.2024	SOP 104 (ČSN EN ISO 5165, ASTM D613)		
First digit describes whether the test was performed within the accreditation range of the testing laboratory 1152.1: 1 = test within the scope of accreditation; 2 = test outside the scope of accreditation. Second digit represents the testing location: 1=Prague laboratory, U Trati 42, Prague 10; 2=Kolín laboratory, Ovčárecká 314, Kolín 5; 9=outside contractor (f) – test procedure changed within the flexible scope of accreditation							
Note	s and deviations						

Testing method	Commentary					
SOP 104 (ČSN EN ISO 5165, ASTM D613)	Testing engine Waukesha CFR F-5, extended measurement uncertainty - 1 unit of cetane number. For the test were used reference fuels U-32 and T-32.					

Extended measurement uncertainty is a product of standard measurement uncertainty and an extension coefficient k=2 which corresponds to about 95% coverage probability for standard distribution

- END OF LABORATORY REPORT -